


CNC720 Breakout


Contents:

Each breakout board kit contains the following:

- ✓ 1x Breakout Board CNC720
- ✓ 4x PCB Spacer 19 mm
- ✓ 4x PCB Spacer 8 mm
- ✓ 8x Screw M3 6 mm



Overview:




Installation:


The kit contains all the mounting material to mount a CNC720 controller and breakout board.

Step 1. Create mounting holes

The first step is to make holes for mounting the CNC760. On our website, the dimensions can be found.




Step 2. Mount bottom spacers




Step 3. Mount CNC720



Step 5. Mount top spacers



Step 6. Mount the breakout board and fix the board with the four M3 screws



You're done !

Setup:

The switch used for the HOME sensor can be connected to GND or 24V, this can be selected by the jumper on the breakout board.

